


Contents Included | Contenu inclus



USB 3.0 A to B
USB 3.0 A à B



Universal Power Supply
Alimentation électrique universell

Quick Start Guide for Mac®

Windows® users please visit www.g-technology.com/support




Guide de démarrage rapide pour Mac®

Utilisateurs de Windows®, visitez le site www.g-technology.com/support




Setting Up Your G-DRIVE USB

- 1 Remove your G-DRIVE USB from its packaging. G-DRIVE USB easily attaches to your computer via the USB 3.0/2.0 port. Simply use the USB cable to connect the drive to the USB port on your computer.



- 2 Plug in the power adapter and press the power switch on the back of the G-DRIVE USB to power up the device. The LED indicator on the front of the G-DRIVE USB unit will light up.



- 3 After a few moments your G-DRIVE USB will appear as a drive on your desktop.
- 4 If you wish to disconnect your G-DRIVE USB, please eject the drive prior to powering down and disconnecting the cables.

Notes:


If you have any questions about G-DRIVE USB, or would like to download the full product manual, visit www.g-technology.com/support

The indicator light on the unit will glow when power is applied and will flash brighter as data is transferred to or from the hard drive.


For information on configuring and using your drive with Windows, please visit www.g-technology.com/support

Configuration de votre disque dur G-DRIVE USB

- 1 Retirez votre USB G-DRIVE de son emballage. L'USB G-DRIVE se branche facilement sur votre ordinateur sur le port USB 3.0/2.0. Utilisez tout simplement le câble USB pour brancher le disque sur le port USB de votre ordinateur.



- 2 Branchez l'adaptateur de courant et appuyez sur l'interrupteur de tension à l'arrière du G-DRIVE USB afin de le mettre en marche. Le voyant DEL à l'avant de l'appareil G-DRIVE USB s'allumera.



- 3 Après un court moment, votre G-DRIVE USB apparaîtra comme un lecteur sur votre bureau.
- 4 Si vous désirez déconnecter votre G-DRIVE USB, veuillez l'éjecter avant de débrancher les câbles.

Remarques :

Si vous avez des questions au sujet du G-DRIVE USB ou si vous désirez télécharger le manuel complet du produit, visitez le site www.g-technology.com/support

Le voyant d'activité situé de l'appareil s'allume lorsque celui-ci est alimenté, puis il clignote et devient plus brillant lors du transfert de données.

Pour obtenir de l'information sur la configuration ou l'utilisation de votre disque dur avec Windows, visitez le site www.g-technology.com/support